


Thank you for purchasing a ZTechnik Product. Please read these instructions carefully and thoroughly before beginning work. Dealers if installing this windshield for a customer please give them this manual. It contains information needed to properly maintain and use this product.



Attention:

Special notes and cautionary measures which can prevent damage to the accessory or motorcycle.





TOOL REQUIRED: 3mm Hex Key

N SEN

Note:

Tips for facilitation of operation, control and adjustment, as well as maintenance work.

KIT CONTAINS ONE OF THE FOLLOWING WINDSCREENS

Item	Description	Qty.
1	Z2410, Windscreen Sport, Dark Tint	1
1	Z2411, Windscreen Touring, Light Tint	1
1	Z2412, Windscreen Tall, +3", Clear	1
1	Z2413, Windscreen, Tall, +7", Clear	1
BAG 1001, Contained in all Kits		
BAG 10	001, Contained in all Kits	
2 2	44-447635-000, Washer with Adhesive	4
2 3	,	4
2 3 4	44-447635-000, Washer with Adhesive	<u> </u>
2 3 4 5	44-447635-000, Washer with Adhesive 51-514130-000, Screw M5 x 30	4

PREPARATION

1. Remove the stock windshield. Parts will not be reused.



➤ Right and Left of motorcycle are determined from the rider's perspective while sitting on the motorcycle.

ZTechnik PO Box 158 Maywood, IL 60153-0158 USA

708-343-0400 / Fax: 708-343-0625 / www.Z Technik.com / e mail: info@Z Technik.com

©2009 National Cycle, Inc.

Page 1 of 2

10-118554-000 12/09





Figure 1



Figure 2




Figure 3

INSTALLATION

- 1. Remvoe the backing paper from a Washer (2) and apply washer to the Flat Side of a Cap (4). Repeat procedure for remaining Washers. **Figure 1**
- 2. Insert a Screw (3) through each Cap Assembly. Figure 2
- **3.** From the Inside, install the Large Standoff (6) into the **Upper Right Hole** of the Windshield. **Figure 3**
- **4.** Install the Windshield to motorcycle using the Screw Assemblies and remaing Short Standoffs (5). **3mm Hex Key Figure 4.**
- 5. Tighten Screws firmly, do not overtighten.

MAINTENANCE

To clean the screen, wash with a clean soft cloth, plenty of warm water and if necessary, a non-abrasive soap such as dishwashing liquid. Flannel or soft chamois make good cleaning cloths. **Paint, glue residue or grease removal:** Moisten cotton with Naphtha or Turpentine followed by a wash as above. National Cycle Shield Wash™ makes a good daily cleaner and comes with a handy travel size bottle. N1401 Shield Wash is safe for helmet visors.

Do not clean polycarbonate in hot sun or high temperatures. Do not clean the screen with glass cleaners. Do not use rain protective products on the screen. Do not allow brake fluid, alcohol, or strong solvents to contact the screen.



VStream® windshield patent no. 7,387,328



ZTechnik 3-Year Limited Warranty Register your windshield on Line at: www.ZTechnik.com

ZTechnik hereby warrants to the original registered owner of a ZTechnik polycarbonate windshield for a period of three years from the date of purchase against breakage. This limited warranty is expressly limited to the replacement of the polycarbonate windscreen. This limited warranty does not include scratches, coating failure, cosmetic wear and tear, replacement of hardware, or any consequential damages or expenses including labor cost of installation, removal and/or replacement, inconvenience, inbound freight expenses or damage to any other component of

the motorcycle or any other accessories. Certain chemicals, generally known as acidic hydrocarbons, are known to cause polycarbonate damage and will not be covered under this limited warranty. Please refer to the cleaning instructions supplied with all ZTechnik windshields.

Visit www.ZTechnik.com for further details are call or write ZTechnik / PO Box 158 / Maywood, IL 60153 / 708-3430400